

ESPAM2.1 Depletion Factors (AKA Response Functions)


Allan Wylie IDWR 6 May, 2014















Outline

- Why a transient depletion factor database
 - Response function = depletion factor
- Development of the database
- Distribution of the database
- How IDWR intends to use the database
- How to obtain the database













Why a transient depletion factor database

- The Idaho Water Resource Board (IWRB) received funding to support aquifer enhancement activities.
- Several requests from the IWRB for analyses that could be conducted using a transient depletion factor database.













Development of the database

- Transient depletion factors
 - Calculated for every active model cell
 - 1st stress period=30 day injection of 1.2 cfs
 - 2nd stress period=40 yr of no injection
 - 487 30 day time steps
 - Calculate fraction of injected volume exiting aquifer for each reach at each time step
 - 799 MB in zipped text files, 12.2 GB in database
- Steady state and transient depletion factors are on the ESHMC web page
 - http://www.idwr.idaho.gov/Browse/WaterInfo/E
 SPAM/model_files/Version_2.1_Current/
















Use of database


- Evaluation of potential Water Board Sponsored recharge sites
 - Produce depletion factors for individual model cells
 - Produce charts sowing fate of water at specific time after injection
 - Produce maps showing depletion factor at specific times










	F 1 2	₹ ₹						Воо	k1 - Microse	oft Excel			_					X
	Home	Insert	Page Layou	t Formu	las Dat	a Reviev	v View	Develop	er								②	_ = X
	A63	N + (P f _s	4/20/19	05	R	W	L										×
	A	В	С	D	Е	F	G	Н	1	J	K	L	M	N	0	Р	Q	R
_	12/2/1902	0.000144	0.002317	5.99E-05	0.004482	4.03E-05	0.012008	0.04884	0.000798	0.029685	0.03356	1.42E-05	3.75E-05	4.27E-05	6.78E-06	0.000141	5.81E-07	0.0002
3.	5 1/1/1903	0.000159	0.00235	6.16E-05	0.004552	4.09E-05	0.012246	0.049532	0.00081	0.030104	0.034034	1.45E-05	3.82E-05	4.35E-05	6.91E-06	0.000144	5.92E-07	0.0002
	5 1/31/1903		0.002382	6.34E-05	0.004619	4.16E-05	0.012478	0.050202	0.000821	0.030509	0.034494	1.47E-05	3.89E-05	4.43E-05	7.04E-06	0.000147	6.03E-07	0.000
	7 3/2/1903		0.002412	6.51E-05	0.004684	4.22E-05	0.012704	0.050851	0.000831	0.030902	0.034939	1.5E-05	3.96E-05	4.51E-05	7.16E-06	0.000149	6.13E-07	0.0002
	8 4/1/1903		0.002442			4.27E-05	0.012924	0.051481	0.000841	0.031283	0.03537	1.53E-05	4.02E-05	4.58E-05	7.28E-06	0.000152	6.23E-07	0.0002
⊪—	5/1/1903		0.002471	6.83E-05	0.004808	4.33E-05	0.013138	0.052091	0.000851	0.031653	0.035789	1.55E-05	4.09E-05	4.65E-05	7.4E-06	0.000154	6.33E-07	0.0002
-	5/31/1903	0.000247		6.99E-05	0.004868	4.39E-05	0.013347	0.052684	0.000861	0.032011	0.036195	1.57E-05	4.15E-05	4.73E-05	7.51E-06	0.000156	6.43E-07	0.0002
	1 6/30/1903		0.002526	7.14E-05	0.004926	4.44E-05	0.013551	0.053259	0.00087	0.032359	0.03659	1.6E-05	4.21E-05	4.79E-05	7.62E-06	0.000159	6.52E-07	0.0002
-	2 7/30/1903		0.002553	7.29E-05	0.004982	4.49E-05	0.01375	0.053818	0.000879	0.032698	0.036973	1.62E-05	4.27E-05	4.86E-05	7.73E-06	0.000161	6.62E-07	0.0002
-	8/29/1903		0.002578	7.44E-05		4.54E-05	0.013944	0.054362	0.000888	0.033027	0.037346	1.64E-05	4.33E-05 4.38E-05	4.93E-05	7.83E-06	0.000163	6.7E-07	0.0002
-	4 9/28/1903	0.00033	0.002603	7.58E-05 7.72E-05	0.005089	4.59E-05 4.64E-05	0.014133	0.05489	0.000897	0.033347	0.037709	1.66E-05 1.68E-05	4.38E-05 4.44E-05	4.99E-05 5.05E-05	7.93E-06 8.03E-06	0.000165	6.79E-07 6.88E-07	0.0002
_	5 10/28/1903 5 11/27/1903		0.002628	7.72E-05 7.85E-05	0.005141	4.64E-05 4.69E-05	0.014318	0.055405	0.000903	0.033658	0.038062	1.7E-05	4.44E-05 4.49E-05	5.05E-05 5.11E-05	8.13E-06	0.000167	6.88E-07 6.96E-07	0.0002
-	7 12/27/1903		0.002631	7.99E-05	0.00524	4.03E-03 4.73E-05	0.014433	0.056393	0.000913	0.033301	0.03874	1.72E-05	4.49E-05	5.17E-05	8.22E-06	0.000103	7.04E-07	0.0002
	3 1/26/1904		0.002673	8.12E-05	0.005288	4.77E-05	0.014847	0.056868	0.000921	0.034544	0.039066	1.74E-05	4.59E-05	5.23E-05	8.32E-06	0.000171	7.12E-07	0.0002
-	2/25/1904		0.002037	8.24E-05	0.005334	4.82E-05	0.015016	0.057331	0.000937	0.034824	0.039384	1.76E-05	4.64E-05	5.29E-05	8.41E-06	0.000175	7.19E-07	0.0002
	3/26/1904	0.000478	0.00274	8.37E-05	0.00538	4.86E-05		0.057782	0.000944	0.035098	0.039694	1.78E-05	4.69E-05	5.34E-05	8.49E-06	0.000177	7.27E-07	0.0003
-	1 4/25/1904		0.002761	8.49E-05	0.005424	4.9E-05	0.015341	0.058223	0.000951	0.035364	0.039996	1.8E-05	4.74E-05	5.4E-05	8.58E-06	0.000179	7.34E-07	0.0003
-	2 5/25/1904	0.000533	0.002781	8.61E-05	0.005467	4.94E-05	0.015499	0.058652	0.000958	0.035624	0.040291	1.82E-05	4.79E-05	5.45E-05	8.66E-06	0.00018	7.41E-07	0.0003
	3 6/24/1904		0.002801	8.72E-05	0.005509	4.98E-05	0.015653	0.059071	0.000965	0.035878	0.040579	1.83E-05	4.83E-05	5.5E-05	8.74E-06	0.000182	7.48E-07	0.000
5	4 7/24/1904	0.00059	0.002821	8.84E-05	0.00555	5.02E-05	0.015803	0.05948	0.000972	0.036126	0.04086	1.85E-05	4.87E-05	5.55E-05	8.82E-06	0.000184	7.55E-07	0.0003
5.	8/23/1904	0.000619	0.00284	8.95E-05	0.00559	5.05E-05	0.015951	0.05988	0.000978	0.036367	0.041134	1.87E-05	4.92E-05	5.6E-05	8.9E-06	0.000185	7.62E-07	0.0003
5	5 9/22/1904	0.000649	0.002858	9.06E-05	0.005629	5.09E-05	0.016095	0.06027	0.000985	0.036604	0.041402	1.88E-05	4.96E-05	5.65E-05	8.98E-06	0.000187	7.68E-07	0.0003
5	7 10/22/1904	0.000679	0.002876	9.17E-05	0.005667	5.13E-05	0.016236	0.060651	0.000991	0.036834	0.041664	1.9E-05	5E-05	5.69E-05	9.05E-06	0.000188	7.75E-07	0.0003
5	3 11/21/1904	0.00071	0.002894	9.27E-05	0.005705	5.16E-05	0.016374	0.061024	0.000997	0.03706	0.04192	1.91E-05	5.04E-05	5.74E-05	9.12E-06	0.00019	7.81E-07	0.0003
5	12/21/1904	0.000742	0.002911	9.37E-05	0.005741	5.19E-05	0.016509	0.061388	0.001003	0.03728	0.04217	1.93E-05	5.08E-05	5.78E-05	9.19E-06	0.000191	7.87E-07	0.0003
6	1/20/1905	0.000774	0.002928	9.47E-05	0.005777	5.23E-05	0.016641	0.061744	0.001009	0.037496	0.042415	1.94E-05	5.12E-05	5.83E-05	9.26E-06	0.000193	7.93E-07	0.0003
6	1 2/19/1905	0.000806	0.002944	9.57E-05	0.005812	5.26E-05	0.016771	0.062092	0.001014	0.037707	0.042654	1.96E-05	5.16E-05	5.87E-05	9.33E-06	0.000194	7.99E-07	0.0003
6	2 3/21/1905	0.000839	0.00296	9.67E-05	0.005846	5.29E-05	0.016898	0.062432	0.00102	0.037913	0.042888	1.97E-05	5.19E-05	5.91E-05	9.4E-06	0.000196	8.04E-07	0.0003
6		0.000872	0.002976	9.76E-05	0.005879	5.32E-05	0.017022	0.062765	0.001025	0.038114	0.043117	1.98E-05	5.23E-05	5.95E-05	9.46E-06	0.000197	8.1E-07	0.0003
	4 5/20/1905	0.000906	0.002992	9.86E-05	0.005912	5.35E-05	0.017144	0.063091	0.001031	0.038312	0.043341	2E-05	5.26E-05	5.99E-05	9.53E-06	0.000198	8.15E-07	0.0003
	5 6/19/1905		0.003007	9.95E-05	0.005944	5.38E-05	0.017263	0.06341	0.001036	0.038505	0.04356	2.01E-05	5.3E-05	6.03E-05	9.59E-06	0.0002	8.21E-07	0.000
-	5 7/19/1905	0.000975	0.003021	0.0001	0.005975	5.41E-05	0.01738	0.063722	0.001041	0.038694	0.043775	2.02E-05	5.33E-05	6.07E-05	9.65E-06	0.000201	8.26E-07	0.0003
	7 8/18/1905		0.003036	0.000101	0.006006	5.44E-05	0.017494	0.064028	0.001046	0.038879	0.043985	2.04E-05	5.36E-05	6.11E-05	9.71E-06	0.000202	8.31E-07	0.0003
-	9/17/1905	0.001045	0.00305	0.000102	0.006036	5.47E-05	0.017606	0.064327	0.001051	0.03906	0.044191	2.05E-05	5.4E-05	6.14E-05	9.77E-06	0.000203	8.36E-07	0.0003
	9 10/17/1905	0.001081	0.003064	0.000103	0.006065	5.49E-05	0.017716	0.06462	0.001056	0.039237	0.044392	2.06E-05	5.43E-05	6.18E-05	9.82E-06	0.000204	8.41E-07	0.0003
_	11/16/1905	0.001117		0.000104	0.006094	5.52E-05	0.017824	0.064907	0.00106	0.039411	0.044589	2.07E-05	5.46E-05	6.22E-05	9.88E-06	0.000206	8.45E-07	0.0003
-	1 12/16/1905		0.003091	0.000105	0.006122	5.55E-05	0.017929	0.065189	0.001065	0.039581	0.044783	2.08E-05	5.49E-05	6.25E-05	9.93E-06	0.000207	8.5E-07	0.0003
-	2 1/15/1906 3 2/14/1906		0.003104	0.000105	0.006149	5.57E-05 5.6E-05	0.018033	0.065464	0.001069	0.039748	0.044972	2.09E-05 2.11E-05	5.52E-05 5.55E-05	6.28E-05 6.32E-05	9.99E-06 1E-05	0.000208	8.55E-07 8.59E-07	0.0003
-	4 3/16/1906	0.001227		0.000106	0.006203	5.62E-05	0.018134	0.065734	0.001074	0.039912	0.045158	2.11E-05 2.12E-05	5.58E-05	6.35E-05	1.01E-05	0.000209	8.59E-07 8.64E-07	0.0003
	5 4/15/1906		0.003129	0.000107	0.006229	5.65E-05	0.018234	0.065999	0.001078	0.040072	0.045518	2.12E-05 2.13E-05	5.6E-05	6.38E-05	1.01E-05	0.00021	8.68E-07	0.0003
	5 5/15/1906		0.003141	0.000108	0.006254	5.67E-05	0.018331	0.066512	0.001082	0.040229	0.045518	2.13E-05 2.14E-05	5.63E-05	6.41E-05	1.01E-05	0.000211	8.72E-07	0.000
	7 6/14/1906			0.000108		5.69E-05		0.066761				2.14E-05 2.15E-05	5.66E-05	6.44E-05	1.02E-05	0.000212	8.76E-07	0.0003
	1	2 / Sheet1			0.000273	5.052-05	3.01032	5.000701	3.00103	5.040554	0.045005	2.131-03	5.00E-05	5.44E-03	1.021-00	0.000213	5.70L-07	0.0003
-	eady 🛅	.z / Sneet1	Sneet3	(6)						Δν	erage: 2/3/19	900 Count	57 Sum: 4	/21/1905		100%	U	(+)
<u> </u>										AV		Count	- Junio					.,






		- PL) =	_	_	_			May2014	FSHMC.xlsx	- Microsoft F	Excel			_	W			■ X			
F) 1 2 3									May2014ESHMC.xlsx - Microsoft Excel									@ _ □ X			
	Home	Insert N	Page Layo		M	A Revi	ew View	/ Devel	per								②				
Ь	A1			f∗ Cell_i														1			
	A	В	С	D	E	F	G	Н	I PRIOCE	J	K	L	M	N	0	Р	Q	R			
1	Cell_ID	ASH_REX						BOX	BRIGGS	BUL_LSF			D030013					D03301			
3	1005106	3.18E-11	1.17E-08	4E-11	1.78E-08	1.51E-10	3.12E-08	2.45E-07	4.04E-09	1.3E-08	1.51E-07	1.67E-07	3.61E-11	9.65E-11	1.1E-10	1.75E-11	3.65E-10	1.5038			
4	1005107 1005108	2.77E-09 3.44E-09	4.48E-08 2.03E-08	5.32E-10 9.25E-11	7.78E-08 3.24E-08	6.82E-10 2.78E-10	1.93E-07 6.81E-08	9.41E-07 4.27E-07	1.54E-08 7.01E-09	6.63E-08 2.55E-08	5.75E-07 2.62E-07	6.5E-07 2.93E-07	2.03E-10 7.11E-11	5.38E-10 1.89E-10	6.13E-10 2.16E-10	9.75E-11 3.44E-11	2.03E-09 7.17E-10	8.3515 2.9488			
5	1005108	3.89E-09	1.6E-08	2.45E-11	2.45E-08	2.78E-10 2.08E-10	4.68E-08	3.36E-07	5.53E-09		2.02E-07 2.06E-07	2.3E-07	4.87E-11	1.3E-10	1.49E-10	2.37E-11	4.94E-10	2.032			
6	1005105	8.92E-10	2.09E-08	1.29E-10	3.38E-08	2.92E-10	8.45E-08	4.39E-07	7.21E-09	2.7E-08	2.69E-07	3.03E-07	7.72E-11	2.05E-10	2.34E-10	3.73E-11	7.77E-10	3.195			
7	1006107	2.75E-09	1.9E-08	6.32E-11	2.99E-08	2.56E-10	6.44E-08	3.99E-07	6.56E-09		2.45E-07	2.74E-07	6.34E-11	1.69E-10	1.93E-10	3.08E-11	6.41E-10	2,6365			
8	1006107	6.97E-09	4.5E-08	5.03E-10	7.77E-08	6.8E-10	1.94E-07	9.46E-07	1.55E-08		5.78E-07	6.54E-07	2E-10	5.3E-10	6.04E-10	9.62E-11	2E-09	8.2390			
9	1006109	2.32E-09	2.08E-08	8.41E-11	3.29E-08	2.82E-10	6.37E-08	4.37E-07	7.18E-09		2.68E-07	3E-07	7.1E-11	1.89E-10	2.16E-10	3.44E-11	7.17E-10	2.9488			
10		7.92E-09	5.11E-08	6.05E-10	8.88E-08	7.78E-10	2.25E-07	1.07E-06	1.76E-08		6.56E-07	7.42E-07	2.31E-10	6.13E-10	6.99E-10	1.11E-10	2.32E-09	9.5231			
1:		1.08E-08	5.01E-08	5.55E-10	8.64E-08	7.57E-10	2.15E-07	1.05E-06	1.73E-08		6.43E-07	7.27E-07	2.22E-10	5.89E-10	6.72E-10	1.07E-10	2.23E-09	9.155			
12		2.53E-09	2.45E-08	1.29E-10	3.92E-08	3.37E-10	8.2E-08	5.14E-07	8.44E-09		3.15E-07	3.53E-07	8.71E-11	2.32E-10	2.65E-10	4.22E-11	8.78E-10	3.6131			
13		2.78E-09	3.48E-08	2.23E-10	5.7E-08	4.93E-10	1.25E-07	7.3E-07	1.2E-08		4.47E-07	5.02E-07	1.32E-10	3.52E-10	4.01E-10	6.38E-11	1.33E-09	5.4703			
14	1008107	8.05E-09	5.63E-08	6.59E-10	9.78E-08	8.57E-10	2.46E-07	1.18E-06	1.94E-08	8.32E-08	7.23E-07	8.18E-07	2.54E-10	6.74E-10	7.68E-10	1.22E-10	2.54E-09	1.04€			
15	1008108	9.74E-09	5.93E-08	6.92E-10	1.03E-07	9.02E-10	2.6E-07	1.25E-06	2.04E-08	8.76E-08	7.61E-07	8.61E-07	2.67E-10	7.09E-10	8.08E-10	1.29E-10	2.68E-09	1.1013			
16	1008109	1.89E-09	3.59E-08	2.11E-10	5.87E-08	5.07E-10	1.25E-07	7.54E-07	1.24E-08	4.74E-08	4.62E-07	5.19E-07	1.35E-10	3.58E-10	4.08E-10	6.5E-11	1.35E-09	5.5695			
17	1008110	1.39E-08	7.37E-08	8.84E-10	1.28E-07	1.12E-09	3.26E-07	1.55E-06	2.54E-08	1.09E-07	9.45E-07	1.07E-06	3.35E-10	8.88E-10	1.01E-09	1.61E-10	3.35E-09	1.3798			
18	1008111	3.23E-09	4.43E-08	2.51E-10	7.21E-08	6.22E-10	1.53E-07	9.3E-07	1.53E-08	5.81E-08	5.69E-07	6.4E-07	1.64E-10	4.37E-10	4.99E-10	7.94E-11	1.65E-09	6.806€			
19	1009107	1.89E-08	4.13E-08	3.77E-10	6.93E-08	6.02E-10	1.53E-07	8.67E-07	1.42E-08	5.72E-08	5.3E-07	5.96E-07	1.7E-10	4.51E-10	5.14E-10	8.19E-11	1.71E-09	7.0167			
20	1009108	1.4E-10	3.95E-08	2.47E-10	6.46E-08	5.58E-10	1.44E-07	8.28E-07	1.36E-08	5.23E-08	5.07E-07	5.71E-07	1.49E-10	3.97E-10	4.53E-10	7.21E-11	1.5E-09	6.1803			
2:	1009109	1.03E-08	4.91E-08	3.72E-10	8.16E-08	7.08E-10	1.86E-07	1.03E-06	1.69E-08	6.7E-08	6.31E-07	7.11E-07	1.95E-10	5.17E-10	5.89E-10	9.39E-11	1.95E-09	8.040			
22	1009110	1.02E-08	6.21E-08	5.32E-10	1.04E-07	9.07E-10	2.4E-07	1.3E-06	2.14E-08	8.66E-08	7.97E-07	8.99E-07	2.55E-10	6.76E-10	7.71E-10	1.23E-10	2.56E-09	1.051€			
23	1009111	6.54E-09	8.56E-08	8.64E-10	1.46E-07	1.28E-09	3.49E-07	1.8E-06	2.95E-08	1.23E-07	1.1E-06	1.24E-06	3.69E-10	9.8E-10	1.12E-09	1.78E-10	3.7E-09	1.522			
24	1009112	2.26E-08	1.28E-07	1.55E-09	2.24E-07	1.96E-09	5.65E-07	2.69E-06	4.42E-08	1.91E-07	1.65E-06	1.86E-06	5.86E-10	1.55E-09	1.77E-09	2.82E-10	5.86E-09	2.4118			
25	1010107	1.23E-08	7.68E-08	9.45E-10	1.34E-07	1.18E-09	3.45E-07	1.61E-06	2.65E-08	1.15E-07	9.86E-07	1.12E-06	3.52E-10	9.34E-10	1.06E-09	1.69E-10	3.53E-09	1.4502			
26	1010108	1.57E-08	8.72E-08	9.86E-10	1.51E-07	1.32E-09	3.76E-07	1.83E-06	3E-08	1.28E-07	1.12E-06	1.27E-06	3.9E-10	1.03E-09	1.18E-09	1.88E-10	3.91E-09	1.6074			
27	1010109	2.05E-08	1.11E-07	1.38E-09	1.95E-07	1.71E-09	4.97E-07	2.34E-06	3.84E-08	1.67E-07	1.43E-06	1.62E-06	5.13E-10	1.36E-09	1.55E-09	2.47E-10	5.13E-09	2.1115			
28	1010110	5.32E-09	8.81E-08	7.65E-10	1.49E-07	1.29E-09	3.44E-07	1.85E-06	3.04E-08	1.24E-07	1.13E-06	1.28E-06	3.65E-10	9.68E-10	1.1E-09	1.76E-10	3.66E-09	1.505			
29		2.67E-08	1.51E-07	1.87E-09	2.64E-07	2.32E-09	6.73E-07	3.17E-06	5.2E-08		1.94E-06	2.19E-06	6.96E-10	1.84E-09	2.1E-09	3.34E-10	6.96E-09	2.8635			
30		3.26E-08	1.76E-07	2.21E-09	3.09E-07	2.71E-09	7.89E-07	3.7E-06	6.07E-08		2.26E-06	2.56E-06	8.16E-10	2.16E-09	2.46E-09	3.92E-10	8.16E-09	3.3568			
3:		1.86E-08	1.2E-07	1.27E-09	2.06E-07	1.8E-09	5.05E-07	2.52E-06	4.13E-08		1.54E-06	1.74E-06	5.26E-10	1.4E-09	1.59E-09	2.53E-10	5.27E-09	2.1692			
32		2.92E-08	1.39E-07	1.49E-09	2.4E-07	2.1E-09	5.83E-07	2.92E-06	4.8E-08		1.79E-06	2.02E-06	6.14E-10	1.63E-09	1.85E-09	2.95E-10	6.15E-09	2.5285			
33		3.38E-08	1.93E-07	2.39E-09	3.37E-07	2.96E-09	8.57E-07	4.05E-06	6.63E-08		2.47E-06	2.8E-06	8.9E-10	2.36E-09	2.69E-09	4.28E-10	8.9E-09	3.6620			
34		3.22E-08	2.03E-07	2.26E-09	3.52E-07	3.08E-09	8.78E-07	4.27E-06	7E-08	3E-07	2.61E-06	2.95E-06	9.08E-10	2.41E-09	2.74E-09	4.37E-10	9.1E-09	3.7415			
35		5.05E-08	2.98E-07	3.79E-09	5.23E-07	4.6E-09	1.33E-06	6.26E-06	1.03E-07	4.5E-07	3.82E-06	4.33E-06	1.39E-09	3.68E-09	4.19E-09	6.67E-10	1.39E-08	5.7087			
36		8.07E-08	4.31E-07	5.81E-09	7.63E-07	6.72E-09	1.96E-06	9.07E-06	1.49E-07	6.6E-07	5.53E-06	6.27E-06	2.05E-09	5.43E-09	6.19E-09	9.84E-10	2.05E-08	8.4283			
37		3.86E-08	1.84E-07	1.99E-09	3.19E-07	2.79E-09	7.8E-07	3.88E-06	6.36E-08		2.37E-06	2.68E-06	8.17E-10	2.17E-09	2.47E-09	3.93E-10	8.18E-09	3.3638			
38		5.47E-08	2.75E-07	3.6E-09	4.85E-07	4.26E-09	1.24E-06	5.78E-06	9.48E-08			4E-06	1.29E-09	3.43E-09	3.9E-09	6.21E-10	1.29E-08	5.3204			
39		5.39E-08	3.2E-07	4.16E-09	5.63E-07	4.95E-09	1.44E-06	6.72E-06	1.1E-07		4.1E-06	4.65E-06	1.5E-09	3.98E-09	4.53E-09	7.21E-10	1.5E-08	6.1731			
40		6.78E-08	3.76E-07	4.84E-09	6.61E-07	5.81E-09	1.69E-06	7.9E-06	1.29E-07	5.7E-07	4.82E-06	5.46E-06	1.76E-09	4.66E-09	5.31E-09	8.46E-10	1.76E-08	7.2409			
4:		8.44E-08	4.98E-07	6.72E-09	8.81E-07	7.76E-09	2.27E-06	1.05E-05	1.72E-07		6.39E-06	7.24E-06	2.37E-09	6.28E-09	7.15E-09	1.14E-09	2.37E-08	9.7432			
42		1.33E-07	6.59E-07	9.11E-09	1.17E-06	1.03E-08	3.03E-06	1.39E-05	2.27E-07	1.01E-06	8.45E-06	9.59E-06	3.16E-09	8.37E-09	9.54E-09	1.52E-09	3.16E-08	1.3000			
43		1.73E-07	8.81E-07	1.24E-08	1.57E-06	1.38E-08	4.07E-06	1.85E-05	3.04E-07		1.13E-05 3.65E-06	1.28E-05	4.26E-09	1.13E-08	1.28E-08	2.04E-09	4.25E-08	5.252			
44		4.24E-08	2.84E-07	3.4E-09	4.96E-07	4.36E-09	1.26E-06	5.97E-06	9.8E-08	4.26E-07	3.03E-06	4.13E-06	1.3E-09	3.45E-09	3.93E-09	6.25E-10	1.3E-08	5.35			
		Pivot_10450	53 Join	_1045053		r_Pivot 5	yr_Join /	€ ⊒ /								1000/	U	→ I			
K	ady 🛅															100%	<u> </u>	• .			




















Summary

- Database of transient depletion factors
 - 30 day injection of 1.2 cfs
 - 40 yr of no injection
- Available on ESHMC web page
 - 799 MB in zipped text files
 - 12.2 GB in SQL database
- Produce
 - Aquifer retention curves
 - Pie charts illustrating
 - » Remaining in aquifer at specific date
 - » Where primary exit point is
 - Maps showing depletion factors at a specific date











End